MONTANA WELL LOG REPORT

This well log reports the activities of a licensed Montana well driller, serves as the official record of work done within the borehole and casing, and describes the amount of water encountered. This report is compiled electronically from the contents of the Ground Water Information Center (GWIC) database for this site. Acquiring water rights View scanned well log (5/8/2023 2:24:43 PM) is the well owner's responsibility and is NOT accomplished by the filing of this report.

Other Options Return to menu

Plot this site in State Library Digital Atlas Plot this site in Google Maps

Site Name: ARNOLD, DAN AND LETICIA

GWIC Id: 326359

Section 1: Well Owner(s)

1) ARNOLD, DAN AND LETICIA (MAIL) 1563 SOUTH PINE LAKE ROAD MONTGOMERY TX 77316 [05/08/2023] 2) ARNOLD, DAN AND LETICIA (WELL) 7159 LAKE CREEK ROAD TROY MT 59935 [05/08/2023] 3) MASSEY, RON (WELL) 7159 LAKE CREEK ROAD TROY MT 59935 [06/23/2021]

Section 2: Location

Township Section **Quarter Sections** Range 30N 33W 20 Geocode County LINCOLN Latitude Longitude Geomethod **Datum** -115.8486767445 NAD83 48.3487702636 TRS-SEC **Ground Surface Altitude Ground Surface Method Datum Date**

Addition **Block** Lot

Section 3: Proposed Use of Water

DOMESTIC (1)

Section 4: Type of Work

Drilling Method: Status: NEW WELL

Section 5: Well Completion Date

Date well completed: N/A

Section 6: Well Construction Details

There are no borehole dimensions assigned to this well. There are no casing strings assigned to this well.

There are no completion records assigned to this well.

Annular Space (Seal/Grout/Packer)

There are no annular space records assigned to this well.

Section 7: Well Test Data

Total Depth:

Static Water Level: 133 Water Temperature:

* During the well test the discharge rate shall be as uniform as possible. This rate may or may not be the sustainable yield of the well. Sustainable yield does not include the reservoir of the well casina.

Section 8: Remarks

ORIGINAL DRILLER UNKNOWN. WELL PUMP TEST PERFORMED BY UNIVERSAL DRILLING 6/23/2021. PUMP SET AT 180 FEET; 20 GPM; RECOVER WATER LEVEL 133.

Section 9: Well Log **Geologic Source**

Unassigned Lithology Data

There are no lithologic details assigned to this well.

Driller Certification

All work performed and reported in this well log is in compliance with the Montana well construction standards. This report is true to the best of my knowledge.

Name: Company: License No: -Date Completed: