# MONTANA WELL LOG REPORT

This well log reports the activities of a licensed Montana well driller, serves as the official record of work done within the borehole and casing, and describes the amount of water encountered. This report is compiled electronically from the contents of the Ground Water Information Center (GWIC) database for this site. Acquiring water rights is the well owner's responsibility and is NOT accomplished by the filing of this report.

# **Other Options**

Return to menu Plot this site on a topographic map View scanned well log (7/30/2008 10:07:13 AM)

Site Name: BIDDLE BUD

**GWIC Id: 187863 DNRC Water Right:** 

Section 1: Well Owner(s)

1) BIDDLE, BUD (MAIL) 17375 BULL LAKE RD. TROY MT 59935 [07/19/2000]

Section 2: Location

Township Range Section 31N 33W 3

County

Geocode

LINCOLN

Latitude Longitude 48.481472 115.815105

Geomethod TRS-SEC

**Block** 

**Ground Surface Altitude** 

Method **Datum** 

**Quarter Sections** 

NW1/4 SW1/4 NW1/4

Datum

NAD83

Date

Lot

Section 3: Proposed Use of Water

DOMESTIC (1)

Addition

Section 4: Type of Work

Drilling Method: CABLE Status: NEW WELL

Section 5: Well Completion Date

Date well completed: Wednesday, July 19, 2000

Section 6: Well Construction Details

**Borehole dimensions** From To Diameter 0 75

Casing

From	То	Diameter	Wall Thickness	Pressure Rating	Joint	Туре
-2	73	6	0.250			STEEL

Completion (Perf/Screen)

From	То		 Size of Openings	Description
73	73	6		OPEN BOTTOM

Annular Space (Seal/Grout/Packer)

			Cont.
From	То	Description	Fed?
0	0	BENTONITE	

#### Section 7: Well Test Data

Total Depth: 75 Static Water Level: 57 Water Temperature:

## Pump Test \*

Depth pump set for test \_ feet.

20 gpm pump rate with \_ feet of drawdown after 1 hours of

pumping.

Time of recovery <u>0.5</u> hours. Recovery water level 57 feet. Pumping water level 64 feet.

\* During the well test the discharge rate shall be as uniform as possible. This rate may or may not be the sustainable yield of the well. Sustainable yield does not include the reservoir of the well casing.

### Section 8: Remarks

Section 9: Well Log **Geologic Source** 

Unassigned

From	То	Description	
0	0 70 BROWN CLAY & COBBLESTONES		
70		SAND GRAVEL & WATER	

# **Driller Certification**

All work performed and reported in this well log is in compliance with the Montana well construction standards. This report is true to the best of my knowledge.

Name: ALLYN P. BUFF

Company: CLEARWATER DRILLING

License No: WWC-569 Date 7/19/2000

Completed: