USE TYPEWRITER OR BALL POINT PEN

State of Idaho Department of Reclamation

Location Corrected by IDWR To:

WELL DRILLER'S REPORT

T22N R22E Sec. 6 SWNWNE

mound State law requires that this report be filed with the State Reclamat By: mciscell 2012-10-10

| within 30 days after comple | tion or | abando | onment | of the w | | | ĺ |
|------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------|--------|--------------------|--------------|----|-----------|
| 1. WELL OWNER | 7. WATER LEVEL Department of Water Administration | | | | | | |
| Name Boyd Simmons | S | Static water level 2 feet below land surface Flowing? Yes TNo G.P.M. flow 30 | | | | | |
| Address Salmon, Idaho | 1 | Temperature F. Quality | | | | | _ |
| Owner's Permit No. | | Artesian closed-in pressurep.s.i. Controlled by □ Valve □ Cap □ Plug | | | | | |
| 2. NATURE OF WORK | 8. WELL TEST DATA | | | | | | |
| ☐ New well ☐ Deepened ☐ Replacement | ☐ Pump | | | | | | |
| ☐ Abandoned (describe method of abandoning) | | | G.P.M. | | Hours Pumped | | |
| | | | | | | | |
| 3. PROPOSED USE | | | | | | | |
| ☐ Domestic ☐ Irrigation ☐ Test | 9. LITHOLÓGIC LOG | | | | | | |
| | Hole | De | | Wat | | | ter |
| ☐ Municipal ☐ Industrial ☐ Stock | Diam. | From / | To | Brown Clay | | | No |
| 4. METHOD DRILLED | 0 | 4 | // | Gravel-son | 1 | | |
| ☐ Cable ☐ Rotory ☐ Dug ☐ Other | | 19 | 25 | Gravel - Soul | ders | - | |
| 5. WELL CONSTRUCTION | | 35 | 37 | Clay Hordo | | | |
| Diameter of hole | | 43 | 58 | Gray Sands | tone. | | |
| Casing schedule: ☐ Steel ☐ ConcreteThickness Diameter From To | | | | | | | |
| 1350 inches 6 inches feet 56 feet | | | | | · · | | |
| inches inches feet feet inches feet feet | - | | | - | | | |
| inches inches feet feet feet feet inches feet feet | | | | | | | |
| Was a packer or seal used? ☐ Yes ☐ No | | | | | ^ | | |
| Perforated? | | | | | | | _ |
| Size of perforation inches by inches | | | | | | | |
| Number From To perforations 23 feet 33 feet | | | | | - | | |
| perforations feet feet feet | | | | | | | |
| Well screen installed? ☐ Yes ☑ No | | | | | | | |
| Manufacturer's name | | | | | | | |
| Type Model No Diameter Slot size Set from feet to feet | | | | | | _ | |
| Diameter Slot size Set from feet to feet | | | - | | | | |
| Gravel packed? | | | | | | | \dashv |
| Surface seal? Ø Yes □ No To what depth ② feet | | | | | | - | |
| Material used in seal ☐ Cement grout ☑ Puddling clay | $- \blacksquare$ | | | | | | \exists |
| 6. LOCATION OF WELL | | | | 20 | | 士 | |
| Sketch map location must agree with written location. | 10. | | | | | | |
| [N | Wo | ork star | ted | 7-/- 70 finished _ | 7-13- | 70 | - |
| | 11. DRILLER'S CERTIFICATION This well was drilled under my supervision and this report is true to the best of my knowledge. | | | | | | |
| W T | | | | | | | |
| 1 | | | | | | | |
| • | Driller's or Firm's Name | | | | | | |
| County Lemhi 23N - 22-E SE 1/2 Sec. 3/, T. N/2, R. 18 E/ | Dahle Well Drilling 21 Driller's or Firm's Name Box 693 - Salmon Address 0 - Salmon | | | | | | |
| SE 1/4 Sec. 3/, T. 3 N/0, R. 12 E/0 | Address Richard Dakle 9-6-70 Signed By Date | | | | | | |